

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Corsa F--

VIN: VXKUPHMGBN4233398

Odometer Reading: 47786km

License Plate: BM07BDZN

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V9.20

Repair Order Number: --



System Scanned (17)

System	Status/DTC
Built-in Systems Interface (BSI) -- BSI2010_EV	12
Engine ECU -- CMM_V56	0
ABS or ESP -- ESPMK100_UDS	2
Airbags and pretensioners ECU -- RBG_SPEED_UDS	1
Combination instrument -- COMBINE_UDS	0
Parking assist -- AAS_UDS_G6	0
A/C -- BCC	0
Power steering -- DAE_UDS	0
Battery State Of Charge (SOC) control unit -- BECB_GEN2	0
Controls under the steering wheel -- COM2016	1
Steering wheel controls / Integral controls steering wheel -- VCI	1
Multi-function control panel -- FMUX	0
Seatbelt not fastened warning lamps unit -- TNB_2010	0
Multi-function video camera (CMF) -- CVM_3	2
Touchscreen -- EMF_DGT_UDS_GP	2
Radio navigation system/connected audio system remote control (only for 7-inch screen) -- CRT_A	0
Radio navigation or telematic unit (RTx) -- RCC	5



DTC (26)

Built-in Systems Interface (BSI) – BSI2010_EV (12 DTCs)

DTC	Description	Status
U1F3B:87	No communication with multi-function control unit or the warning lamp for seatbelt not fastened	Intermittent
B173D:86	Fault in identifying mechanical/electronic key or hands-free remote control present in reader -- Identifier Invalid	Intermittent
B2ED3:00	Loss of Built-in Systems Interface (BSI) time counter	Present
B1137:15	Right front low beam control fault -- Circuit open or short to positive	Intermittent
B11F0:48	Traceability of the forcing of the maintaining of the low beam headlamps switch-on : Ignore this fault -- Software fault	Intermittent
B133E:15	Rear window relay control output fault -- Circuit open or short to positive	Intermittent
B133D:15	Front window relay control output fault -- Circuit open or short to positive	Intermittent
B1865:23	Inconsistency between status of engine starting switch and status of Built-in Systems Interface (BSI) engine starting authorization output	Present
B1805:62	Starter fault -- Consistency	Intermittent
B1806:62	Cutting out engine when driving fault -- Consistency	Intermittent
B1418:00	Fault in seatbelt fastening information status for determining presence of driver	Intermittent
U1F1A:08	Fault in communication on LIN 1	Intermittent

ABS or ESP – ESPMK100_UDS (2 DTCs)

DTC	Description	Status
C003A:68	Right rear Wheel Speed Sensor (WSS) -- Operation not performed	Intermittent
C0037:68	Left rear Wheel Speed Sensor (WSS) -- Operation not performed	Intermittent

Airbags and pretensioners ECU – RBG_SPEED_UDS (1 DTC)

DTC	Description	Status
B00D5:67	Passenger airbag deactivation LED -- Invalid signal	Intermittent

Controls under the steering wheel – COM2016 (1 DTC)

DTC	Description	Status
B1180:00	Fault in lighting controls -- Not characterized	

Steering wheel controls / Integral controls steering wheel – VCI (1 DTC)

DTC	Description	Status
-----	-------------	--------

U1F1A:87	Fault in transmission by top-of-column on LIN -- Not characterized	Intermittent
----------	--	--------------

Multi-function video camera (CMF) – CVM_3 (2 DTCs)

DTC	Description	Status
U1F00:00	Event not recorded	Intermittent
B1238:00	Field of vision of the multi-function video camera -- Hindering object detected	Intermittent

Touchscreen – EMF_DGT_UDS_GP (2 DTCs)

DTC	Description	Status
B1574:1C	Please refer to vehicle service manual.	
U1FA0:00	Please refer to vehicle service manual.	

Radio navigation or telematic unit (RTx) – RCC (5 DTCs)

DTC	Description	Status
B100C:00	RCC connected audio system electrical supply -- Not characterized	Intermittent
B1517:04	RCC connected audio system (Bluetooth module) -- Internal fault	Intermittent
B1562:12	USB2 port (USB port used) -- Short circuit to positive	Intermittent
B1563:00	USB1 port (USB port used) -- Electrical fault	Intermittent
B1563:12	USB1 port (USB port used) -- Short circuit to positive	Intermittent

Technician Notes

2017294338

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.