



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231218112734
Test Time: 2023-12-18 11:27:34
Technician: Andrick

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/2'/220d_B47/--
VIN: WBA2G72060V297303

Odometer Reading: 178438km
License Plate: HV42SJGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.10

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(18)

System	Status/DTC
DDE (Engine-Diesel Electronics)	 0
EGS (Electronic Transmission Management)	 0
DSC (Dynamic Stability Control)	 1
ACSM (Airbag-Advanced Crash Safety Module)	 0
KOMBI (Instrument Cluster)	 1
FEM (Front Electronic Module)	 5
ZGM (Central Gateway Module)	 5
ICM (Integrated Chassis Management)	 0
EPS (Electric Power Steering)	 0
AMP (Amplifier)	 0
FZD (Roof Function Center)	 3
GWS (Gear Selector Switch)	 0
TCB (Combox Emergency Call)	 0
HUB (Headunit Basis)	 1
CON (Controller)	 0
AHM (Trailer Module)	 2
REM (Rear Electronic Module)	 19
IHKA (Integrated Automatic Heating And A/C System)	 1



**DTC (38)****DSC (Dynamic Stability Control) (1 DTC)**

DTC	Description	Status
480A90	DSC: Roller brake tester mode active	Intermittent

KOMBI (Instrument Cluster) (1 DTC)

DTC	Description	Status
E12C1A	Signal (central locking system and lid status) invalid, transmitter CAS/FEM/BDC	Intermittent

FEM (Front Electronic Module) (5 DTCs)

DTC	Description	Status
030018	Power window, driver's door: deactivation of drive due to overvoltage	Intermittent
80416D	Engine compartment lid contact switch: Open during driving	Intermittent
8041A8	Welcome light repeat lock active	Intermittent
804415	Radio remote control: Battery undervoltage	Permanent
D90D29	Rain-light-solar-condensation sensor: Missing LIN slave	Intermittent

ZGM (Central Gateway Module) (5 DTCs)

DTC	Description	Status
CD0468	ZGM, K-CAN2: communication fault	Intermittent
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent
801C12	Send Power-Down command due to prevented sleeping	Intermittent
801C13	Request reset terminal 30F due to prevented sleeping	Intermittent
801C20	ZGM: central fault memory full - no control-unit fault	Permanent

FZD (Roof Function Center) (3 DTCs)

DTC	Description	Status
801A52	SINE: Fault when adjusting coding data	Permanent
DE8C5E	LIN SINE, communication fault	Permanent
801A55	DWA: The alarm has been activated	Permanent

HUB (Headunit Basis) (1 DTC)

DTC	Description	Status
B7F8C6	CID: Reduction in brightness due to excess temperature	Intermittent

AHM (Trailer Module) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

E54468	AHM, K-CAN: Communications fault	Intermittent
E554F6	KOMBI interface (kilometre reading/range) signal invalid	Intermittent

REM (Rear Electronic Module) (19 DTCs)

DTC	Description	Status
8032B0	Ultrasonic sensor rear outer left, signal line: Line disconnection	Intermittent
8032B8	Ultrasonic sensors rear centre left, signal line: Line disconnection	Intermittent
8032C0	Ultrasonic sensor, rear centre right, signal line: Line disconnection	Intermittent
8032C8	Ultrasonic sensor, rear outer right, signal line Line disconnection	Intermittent
8032D0	Ultrasonic sensor, front outer left, signal line: Line disconnection	Intermittent
8032D8	Ultrasonic sensor, front centre left, signal line: Line disconnection	Intermittent
8032E0	Ultrasonic sensor, front centre right, signal line: Line disconnection	Intermittent
8032E8	Ultrasonic sensor, front outer right, signal line: Line disconnection	Intermittent
804870	Left-hand brake force display (BFD) defective	Intermittent
804871	Right-hand brake force display (BFD) defective	Intermittent
804872	Brake light, left, faulty	Permanent
804874	Brake light, right, faulty	Intermittent
804876	Turn indicator, rear left, faulty	Intermittent
804877	Turn indicator, rear right, faulty	Intermittent
804881	Reversing light, left, faulty	Intermittent
804882	Reversing light, right, faulty	Intermittent
804884	Left-hand tail light 2 defective	Permanent
804886	Right-hand tail light 2 defective	Intermittent
E58468	REM, body CAN2: communication fault	Intermittent

IHKA (Integrated Automatic Heating And A/C System) (1 DTC)

DTC	Description	Status
8011B9	Stratification control: Short circuit to B+ or interruption	Intermittent

Technician Notes

2016204208

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.