

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >/--
VIN: WVVZZZAUZHW155050

Odometer Reading: 101874km
License Plate: NONE plate

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (19)

System	Status/DTC
01 - Engine Control Module 1	3
02 - Transmission electronics	1
03 - Brakes 1	2
08 - Air conditioning	1
09 - Electronic central electric	5
14 - Wheel Damping Electronics	0
15 - Airbag	0
16 - Steering column electronics	0
17 - Instrument cluster	3
19 - Gateway	3
20 - High beam assistant	1
22 - All-wheel drive electronics	0
42 - Driver's door electronics	4
44 - Power steering	3
52 - Passenger's door electronics	3
55 - Headlamp range control	0
5F - Information electronics 1	0
76 - Parking aid	2
A9 - Structure-Borne Sound Actuator	0



DTC (31)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
P003000	O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)	Active/static
P014000	O2 Sensor Circ.,Bank1-Sensor2 No Activity Detected	Active/static
U112300	Databus error value received	Active/static

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P170100	Transmission control unit locked	Active/static

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
B1168F2	Steering angle sensor no initialization	Active/static
C102D00	Tire pressure warning	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (5 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B147A18	Remote control vehicle key 2 Insufficient current	Active/static
B147A54	Remote control key 2 No basic setting	Passive/Sporadic
B131D04	Sirens/alarm horn for anti-theft warning system Faulty	Passive/Sporadic
B142113	Left front seat heater temperature sensor Open circuit	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1301F0	Transmission control module (TCM) not authorized	Active/static
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U105000	Battery monitoring control module No Communication	Active/static
U006500	Vehicle Communication Bus E Performance	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

20 - High beam assistant (1 DTC)

DTC	Description	Status
U111700	Start-up-relevant adaptation not performed	Active/static

42 - Driver's door electronics (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B177501	Door warning light / entry light Electrical error	Active/static
B131FF5	Driver side rear window regulator Voltage supply below lower limit	Passive/Sporadic
B131FF4	Driver side rear window regulator Voltage supply above upper limit	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
B1168F2	Steering angle sensor no initialization	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic

52 - Passenger's door electronics (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1320F5	Passenger side rear window regulator Voltage supply below lower limit	Passive/Sporadic
B1320F4	Passenger side rear window regulator Voltage supply above upper limit	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
-----	-------------	--------

B107F11	Park assist button Short circuit to ground	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

Technician Notes
2017297653

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.