

# DODGE VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/DODGE/JC-Journey/--

VIN: 3C4PDCKG0FT580988

Odometer Reading: 122140

License Plate: DV62LWGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT

Version: V12.10

Serial Number: VB8GJCC01509

Repair Order Number: --

## System Scanned ( 17 )

| System                               | Status/DTC                                                                                                                                                                  |
|--------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ECM(Engine Control Module)           |  0                                                                                       |
| ABS(Anti Lock Brakes)                |  5                                                                                       |
| ORC(Air Bag/Occupant Restraint)      |  0                                                                                       |
| IPC(Instrument Panel Cluster)        |  0                                                                                       |
| TPM(Tire Pressure Monitor)           |  8                                                                                     |
| BCM(Body Controller)                 |  2                                                                                     |
| HVAC(Heat, Ventilation And A/C)      |  0                                                                                     |
| PDM(Passenger Door Module)           |  1                                                                                     |
| SCCM(Steering Column Control Module) |  0                                                                                     |
| AMP(Amplifier)                       |  0                                                                                     |
| PTS(Parktronics)                     |   0 |
| ICS(Integrated Center Stack)         |  2                                                                                     |
| DDM(Driver Door Module)              |  0                                                                                     |
| HFM(Hands Free Module)               |  0                                                                                     |
| HSM(Heated Seat Module)              |  1                                                                                     |
| TGW(Telematic Gateway Radio)         |  1                                                                                     |
| RFH(Radio Frequency Hub)             |  3                                                                                     |

## DTC ( 23 )

### ABS(Anti Lock Brakes) ( 5 DTCs )

| DTC      | Description                            | Status |
|----------|----------------------------------------|--------|
| C212A-16 | System circuit voltage below threshold | Stored |

|          |                                                            |        |
|----------|------------------------------------------------------------|--------|
| C212A-17 | System circuit voltage above threshold                     | Stored |
| C2101-17 | Battery voltage high - circuit voltage above threshold     | Stored |
| C006A-49 | Multi-Axis acceleration sensor internal electronic failure | Stored |
| C006A-62 | Multi-Axis acceleration sensor signal compare failure      | Stored |

**TPM(Tire Pressure Monitor) ( 8 DTCs )**

| DTC      | Description                                                                | Status |
|----------|----------------------------------------------------------------------------|--------|
| C0077-00 | Low tire pressure                                                          | Active |
| B21DD-84 | System voltage - signal below allowable range                              | Stored |
| U0415-00 | Invalid data received from anti-lock brake system (ABS) control module "A" | Stored |
| C151D-00 | Tire pressure sensor location undetermined                                 | Active |
| C1503-96 | Tire pressure sensor 3 component internal failure                          | Active |
| C1501-96 | Tire pressure sensor 1 component internal failure                          | Active |
| C1580-00 | Left/Right side tire pressure sensor location undetermined                 | Active |
| C1581-00 | Front/Rear tire pressure sensor location undetermined                      | Active |

**BCM(Body Controller) ( 2 DTCs )**

| DTC      | Description                                                     | Status |
|----------|-----------------------------------------------------------------|--------|
| U1008-00 | LIN 1 bus                                                       | Stored |
| B16FB-15 | Right front fog lamp control - circuit short to battery or open | Stored |

**PDM(Passenger Door Module) ( 1 DTC )**

| DTC      | Description                                             | Status |
|----------|---------------------------------------------------------|--------|
| B210C-16 | Battery voltage input - circuit voltage below threshold | Stored |

**ICS(Integrated Center Stack) ( 2 DTCs )**

| DTC      | Description                                            | Status |
|----------|--------------------------------------------------------|--------|
| B210E-17 | Battery voltage high - circuit voltage above threshold | Stored |
| B210D-16 | Battery voltage low - circuit voltage below threshold  | Stored |

**HSM(Heated Seat Module) ( 1 DTC )**

| DTC      | Description                                                        | Status |
|----------|--------------------------------------------------------------------|--------|
| B1EB1-1B | Front left seat heater sensor 1-Circuit resistance above threshold | Active |

**TGW(Telematic Gateway Radio) ( 1 DTC )**

| DTC      | Description                                          | Status |
|----------|------------------------------------------------------|--------|
| B210A-16 | System voltage low - circuit voltage below threshold | Stored |

**RFH(Radio Frequency Hub) ( 3 DTCs )**

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|

|          |                                                   |        |
|----------|---------------------------------------------------|--------|
| B1A10-00 | RKE fob 1 battery low                             | Stored |
| B2199-16 | Battery voltage - circuit voltage below threshold | Stored |
| U103C-00 | KIN/IGNM communication                            | Stored |

**Technician Notes**  
2017297678

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.