

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6R0SU025408

Odometer Reading: 44269
License Plate: MM42WZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 4
03 - Brakes 1	 6
04 - Steering Angle Sender	 1
09 - Electronic central electric	 3
15 - Airbag	 5
17 - Instrument cluster	 1
19 - Gateway	 2
25 - Immobilizer	 2
44 - Power steering	 2

DTC (26)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P1602:00/05 634:000	Power supply terminal 30 Voltage too low	Passive/Sporadic
P0135:00/00 309:000	O2 Sensor Heater Circ.,Bank1-Sensor1 Malfunction	Active/static
P1603:00/05 635:000	Ctrl. module faulty	Passive/Sporadic
P1504:00/05 380:000	Air intake system Leak detected	Active/static

03 - Brakes 1 (6 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

U140000	Function restriction due to low voltage	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic
C114602	TPMS Signal error	Active/static
U101F00	Engine control module (ECM) Read out DTC	Active/static
C101A29	Left front Wheel Speed Sensor (WSS) Range/performance	Active/static

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic

15 - Airbag (5 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B200600	Control module does not match vehicle	Passive/Sporadic
B101600	Front passenger airbag off indicator	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic
03158:004	Information electronics control module 1 - No signal/communication	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U111300	Function limitation due to received malfunction value	Active/static

Technician Notes

2017296789

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.