

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Fortuner/--
VIN: AHTCB8GS802201973

Odometer Reading: 193483
License Plate: LZ82ZHGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 2
SRS airbag	 0
Combination meter	 0
Air conditioner	 0
Entry&Start	 0
Power source control	 0
Starting control	 0
4WD	 0
Radar cruise 1	  0

DTC (4)

Engine and ECT (2 DTCs)

DTC	Description	Status
P0340	Camshaft position (CMP) sensor circuit	History
P1604	Startability fault	History

ABS/VSC/TRC (2 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History

Technician Notes

2017298884

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.