

JETOUR VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/JETOUR/X70 series/X70S/--

VIN: HJRPBGFB5SF011257

Odometer Reading: 37990

License Plate: MB72SGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V14.60

Repair Order Number: --



System Scanned (17)

System	Status/DTC
ECM (Engine system)-Engine Management System (EMS) - China V - 1.5 T	✓ 0
TCU (Transmission Control Unit)-8 A/T	✗ 1
IC (Instrument Cluster)	✗ 9
PEPS (Keyless start system)-BCM/PEPS	✗ 1
ESP (Electronic stability program)	✗ 1
ABM (Airbag Module)-Airbag Module (ABM) Event Data Recorder (EDR)	✓ 0
RADAR (radar system)	ADAS ✓ 0
EPS (Electronic Power Steering System)	✗ 1
IMMO (Immobilizer)	✓ 0
Audio entertainment system (RRM)	✓ 0
TBOX (remote control system)	✗ 6
Steering angle system (SAM)	✓ 0
BM (Bluetooth Module)	✗ 1
APM (Anti-pinch Module)	✓ 0
Left BSD (Blind Spot Detection)	ADAS ✗ 7
PLG (Power Lift Gate)	✓ 0
WPC (wireless charging module)	✗ 12



DTC (39)

TCU (Transmission Control Unit)-8 A/T (1 DTC)

DTC	Description	Status
P17D977	Gear P lock position detection	History

IC (Instrument Cluster) (9 DTCs)

DTC	Description	Status
U0100-87	Lost communication with Engine Management System (EMS) module	Historic Fault Code
U0101-87	Lost communication with Transmission Control Module (TCM) - message lost	Historic Fault Code
U0129-87	Lost communication with Brake System Module (BSM) - message lost	Historic Fault Code
U0131-87	Lost communication with Electric Power Steering (EPS) module - message lost	Historic Fault Code
U015187	Lost communication with ABM (Airbag Controller)	Historic Fault Code
U014187	Lost communication with reverse radar module	Historic Fault Code
U118987	Lost communication with multi-function steering wheel	Historic Fault Code
U0140-87	Lost communication with BCM - message lost	Historic Fault Code
U021487	Lost communication with keyless entry/start system module	Historic Fault Code

PEPS (Keyless start system)-BCM/PEPS (1 DTC)

DTC	Description	Status
B1000-16	Battery voltage - circuit voltage too low	History

ESP (Electronic stability program) (1 DTC)

DTC	Description	Status
C100800	Common Wheel Speed Sensor (WSS) general fault	Historic Fault Code

EPS (Electronic Power Steering System) (1 DTC)

DTC	Description	Status
U010087	Lost communication with Engine Management System (EMS) module	History

TBOX (remote control system) (6 DTCs)

DTC	Description	Status
U118987	CAN Communication Error - Lost Communication with Multifunction Steering System	
U015587	Lost communication with ICM module	
U013187	Lost communication with Electric Power Steering (EPS) controller	
U014087	Lost communication with BCM	
U010087	Lost communication with engine controller	

U012987 Lost communication with brake system controller

BM (Bluetooth Module) (1 DTC)

DTC	Description	Status
C120016	Battery voltage abnormal (voltage low)	History

Left BSD (Blind Spot Detection) (7 DTCs)

DTC	Description	Status
B1A4416	Loop power supply voltage too low	Historic Fault Code
B1A4711	Please refer to vehicle service manual.	Historic Fault Code
B1A4811	Please refer to vehicle service manual.	Historic Fault Code
U012287	ECU lost communication with electronic stability program module	Historic Fault Code
U112287	The engine management system (EMS) is not sending the desired torque signal	Historic Fault Code
U112187	The pedal position signal is not being sent by the engine management system (EMS)	Historic Fault Code
U012187	ABS communication failure, loss of information	Historic Fault Code

WPC (wireless charging module) (12 DTCs)

DTC	Description	Status
B14E017	Please refer to vehicle service manual.	Current DTC
B14E016	Please refer to vehicle service manual.	Current DTC
U007388	CAN bus off	Current DTC
U012487	Please refer to vehicle service manual.	Current DTC
U012587	Please refer to vehicle service manual.	Current DTC
B12E104	Please refer to vehicle service manual.	Current DTC
B14E017	Please refer to vehicle service manual.	History DTC
B14E016	Please refer to vehicle service manual.	History DTC
U007388	CAN bus off	History DTC
U012487	Please refer to vehicle service manual.	History DTC
U012587	Please refer to vehicle service manual.	History DTC
B12E104	Please refer to vehicle service manual.	History DTC

Technician Notes

201729773

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.