

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Eritga/--

VIN: MA3BNC22S00859392

Odometer Reading: 141042

License Plate: LHD680MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V4.91

Repair Order Number: --



System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	5
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	4
CGW(Central gateway control module)	3
EPS(Power steering)	0
BCM(Body Control Module)	2
SMK(Immobilizer and/or keyless system)	2



DTC (16)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (5 DTCs)

DTC	Description	Status
C1027	Electronic stability program off switch circuit fault	History
C1057	Power supply voltage	History
U0100	Lost communication with ECM	History
C1016	Brake lamp switch circuit performance	History
C1037	Steering angle sensor power supply voltage	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (4 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM	History
U0121	Lost communication with ABS or electronic stability program control module	History
U0151	Lost communication with restraints control module	History

B1840 Vehicle speed data invalid

History

CGW(Central gateway control module) (3 DTCs)

DTC	Description	Status
U0100-87	Lost communication with ECM	History
U0151-87	Lost communication with restraints control module	History
U0121-87	Lost communication with ABS or electronic stability program control module	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM	History
U0151	Lost communication with restraints control module	History

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM	History
U0151	Lost communication with restraints control module	History

Technician Notes

2017299135

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.