

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00900218361

Odometer Reading: 99238
License Plate: MC90PDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	 2
ABS(Anti-lock braking system)	 6
ABG(Airbag / pretensioners)	 3
TDB(Instrument panel)	 1
UCH(Central control unit)	 10
DAV(Variable power assist steering)	 1
RDO(Radio)	 4

AQAS

DTC (27)

INJ(Injection) (2 DTCs)

DTC	Description	Status
DTC042009	Catalytic converter functional fault Component in poor condition.	Memory
DTC056016	Computer supply voltage Permanent low level	Memory

ABS(Anti-lock braking system) (6 DTCs)

DTC	Description	Status
DTC402004	Pump motor control circuit Pump fault	Memory
DTC40201C	Pump motor circuit Feed voltage too high	Memory
DTC505004	Computer ECU fault.	Memory
DTC512764	Wheel speed coherence Signal plausibility failure	Memory

DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory
DTCF00313	Computer power supply Open circuit	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Signal low	Memory
DTC80D224	Warning light circuit fault Signal high	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (10 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated Low fluid level	Memory
DTC5A737A	Wheel 2 flat Fluid leak or sealing failure	Memory
DTC5A747A	Wheel 3 flat Fluid leak or sealing failure	Memory
DTC5A757A	Wheel 4 flat Fluid leak or sealing failure	Memory
DTC5A8055	Tire pressure monitor function Not configured	Active
DTC5A8268	Wheel valve sensor 1 Event signal	Memory
DTC5A8368	Wheel valve sensor 2 Event signal	Memory
DTC5A8468	Wheel valve sensor 3 Event signal	Memory
DTC5A8568	Wheel valve sensor 4 Event signal	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory

RDO(Radio) (4 DTCs)

DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC934749	Bluetooth module Internal electronic failure	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes
2017290034

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.