

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >/--
VIN: WVVZZZAUZGW161924

Odometer Reading: 117198km
License Plate: KV58VZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (19)

System	Status/DTC
01 - Engine Control Module 1	 9
02 - Transmission electronics	 0
03 - Brakes 1	 4
08 - Air conditioning	 3
09 - Electronic central electric	 4
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 1
19 - Gateway	 4
22 - All-wheel drive electronics	 1
2B - Steering Column Locking	 2
42 - Driver's door electronics	 4
44 - Power steering	 3
52 - Passenger's door electronics	 6
55 - Headlamp range control	 0
5F - Information electronics 1	 2
76 - Parking aid	 2
A9 - Structure-Borne Sound Actuator	 0
B7 - Interface for access/start system	 3

 DTC (48)

01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
P011700	Coolant temperature sensor 1 Circuit low	Passive/Sporadic
P168C00	Oil pressure switch 3 Implausible signal during engine operation	Passive/Sporadic
P164B00	Oil pressure switch Malfunction	Passive/Sporadic
P305400	Starter does not turn Mechanically blocked or electrical malfunction	Passive/Sporadic
U112300	Databus error value received	Active/static
P16C600	Heater support pump Dry operation	Passive/Sporadic
P218100	Cooling system performance	Active/static
P011600	Coolant temperature sensor 1 Circuit range/performance	Passive/Sporadic
U044700	Invalid data received from serial data gateway module A	Active/static

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B116816	Steering angle sensor Voltage too low	Active/static
C102D00	Tire pressure warning	Passive/Sporadic
C114602	TPMS Signal error	Passive/Sporadic

08 - Air conditioning (3 DTCs)

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic
B10CE00	Blower reduction by energy management	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
B147918	Remote control vehicle key 1 Insufficient current	Active/static

B1330F5	Anti-theft alarm system sensor Alert - emergency activation stage 1	Passive/Sporadic
U112100	Data bus message missing	Active/static
U10F600	Rain/light recognition sensor No communication	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U103000	Local data bus Electrical error	Active/static
U105000	Battery monitoring control module No Communication	Passive/Sporadic
U006500	Vehicle Communication Bus E Performance	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Passive/Sporadic

22 - All-wheel drive electronics (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

2B - Steering Column Locking (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B11D729	Ignition start button Range/performance	Passive/Sporadic

42 - Driver's door electronics (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B122D29	Locking unit for central locking Range/performance	Passive/Sporadic
B131FF5	Driver side rear window regulator Voltage supply below lower limit	Passive/Sporadic
B132102	Driver side rear window regulator motor Signal fault	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic

52 - Passenger's door electronics (6 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B11F814	Heated outside rear-view mirror Open circuit/short circuit to ground	Active/static
B148754	Motor for window regulator No basic setting	Passive/Sporadic
B132513	Ambient illumination lamp Open circuit	Passive/Sporadic
B1320F5	Passenger side rear window regulator Voltage supply below lower limit	Passive/Sporadic
B132202	Passenger side rear window regulator motor Signal fault	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U10BA00	Local data bus No communication	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

B7 - Interface for access/start system (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B116B11	Driver exterior door handle touch sensor Short circuit to ground	Passive/Sporadic

B116C11	Front passenger exterior door handle touch sensor Short circuit to ground	Passive/Sporadic
---------	--	------------------

Technician Notes
2017299370

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.