

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZLU006672

Odometer Reading: 231413
License Plate: MS95SSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
04 - Steering Angle Sender	 0
09 - Electronic central electric	 3
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 1
44 - Power steering	 0
56 - Radio	 2

DTC (6)

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
03429:011	Activation of right cornering light - Open circuit	Active/static
03156:014	Anti-theft alarm system sensor - Faulty	Active/static
03591:011	Signal horn activation - Open circuit	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
00871:011	Right front bass speaker - Open circuit	Passive/Sporadic

01044:000 Control module incorrectly coded

Passive/Sporadic

Technician Notes
2017296379

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.