

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZLU019081

Odometer Reading: 159267
License Plate: JP56RBGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 4
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 1
44 - Power steering	 0
56 - Radio	 3

DTC (9)

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
03429:011	Activation of right cornering light - Open circuit	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
03156:014	Anti-theft alarm system sensor - Faulty	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B200000	Control module faulty	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00870:011	Left front bass speaker - Open circuit	Active/static
00871:011	Right front bass speaker - Open circuit	Active/static
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes
2017287706

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.