

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >--

VIN: AAVZZZAWZKU044630

Odometer Reading: 164724km

License Plate: HMW867FS

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V19.00

Repair Order Number: --



System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	6
03 - Brakes 1	1
08 - Air Conditioning	0
09 - Electronic central electric	2
15 - Airbag	0
17 - Instrument cluster	1
19 - Gateway	0
44 - Power Steering	2
5F - Information electronics 1	1



DTC (13)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
P06E900	Engine Starter Performance	Passive/Sporadic
P06EF00	Engine Restart Performance	Passive/Sporadic
P050100	Vehicle speed sensor A Range/performance	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P109300	Incorrect Fuel Composition	Passive/Sporadic
P125000	Fuel level too low	Active/static

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C1146F2	TPMS EEPROM fault	Active/static

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B104C29	Key Range/performance	Passive/Sporadic

44 - Power Steering (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic

Technician Notes

2016207160

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.