



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260915102403
Test Time: 2026-09-15 10:24:03
Technician: Travino

Chevrolet VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chevrolet/Spark/--
VIN: ADMMF48DLC4602300

Odometer Reading: 225322
License Plate: BY72RVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V34.10

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (4)

System	Status/DTC
Engine control module	✓ 0
Electronic brake control module	✓ 0
Inflatable restraint sensing and diagnostic module	✓ 0
Instrument cluster	✓ 0



DTC (0)

Technician Notes

2017298878

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

