



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260914122216
Test Time: 2026-09-14 12:22:16
Technician: Werner

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Corsa-C/--
VIN: ADMSC08MA83467452

Odometer Reading: 189149
License Plate: BP20XPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (3)

System	Status/DTC
Engine:Y 13 DT	 1
Instrument	 0
Immobiliser	 0

DTC (1)

Engine:Y 13 DT (1 DTC)

DTC	Description	Status
P0562-00	System voltage low	Not present

Technician Notes

2017298445

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

