



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260909113747
Test Time: 2026-09-09 11:37:47
Technician: Andrick

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP300/--
VIN: ADNCPGD22ZR098925

Odometer Reading: 171995
License Plate: MR98VSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
Engine	 0
ABS	 1
Air bag	 0
BCM	 1

DTC (2)

ABS (1 DTC)

DTC	Description	Status
C1111	Pump motor	Current

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2017296439

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.