

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--

VIN: AHTHZ29G102205659

Odometer Reading: 251448

License Plate: HBW290L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V11.80

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (4)

System	Status/DTC
Engine	3
SRS airbag	0
Cruise control	0
Immobilizer	0



DTC (3)

Engine (3 DTCs)

DTC	Description	Status
P1604	Startability fault	Pending
P1604	Startability fault	Current
P1604	Startability fault	History

Technician Notes

2017297655

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.