Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD **KEMPTON PARK** 

Report ID: MAXIA20250127140854 Test Time: 2025-01-27 14:08:54

Technician: Andrick

# Toyota VEHICLE DIAGNOSTIC REPORT

#### **Vehicle Information**

--/Toyota/Corolla/--VIN: AHTLB52E603124448 Odometer Reading: 154838km License Plate: KB43JLGP

**Customer Information** 

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

**Device information** 

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V11.20

Repair Order Number: --

## 🔂 System Scanned( 9 )

| System            |      | Status/DTC |
|-------------------|------|------------|
| Engine and ECT    |      | <b>②</b> 0 |
| ABS/VSC/TRC       |      | <b>Q</b> 1 |
| SRS airbag        |      | <b>②</b> 0 |
| Main body         |      | <b>②</b> 0 |
| Driver door motor |      | <b>②</b> 0 |
| Air conditioner   |      | <b>②</b> 0 |
| Theft deterrent   |      | <b>②</b> 0 |
| EMPS              |      | <b>②</b> 0 |
| Radar cruise 1    | ADAS | <b>②</b> 0 |



### ABS/VSC/TRC (1 DTC)

| DTC   | Description                      | Status  |
|-------|----------------------------------|---------|
| C1241 | Low or high power supply voltage | Current |

## **Technician Notes**

2016736278

www.autel.com MaxiSys MS906 BT Page 1

| Toyota/Corolla | Test Time: 2025-01-27 14:08:54 | Report ID: MAXIA2025012714085 |
|----------------|--------------------------------|-------------------------------|
|----------------|--------------------------------|-------------------------------|

| Customer name: |  |
|----------------|--|
| Technician: _  |  |
| Date:          |  |

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



v.autel.com MaxiSys MS906 BT Page 2