



Shop Name: --

Tel: --

Email: --

Address: --

Report ID: MAXIA20260824090528

Test Time: 2026-08-24 09:05:28

Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--

VIN: AHTSS22P007156333

Odometer Reading: 188415km

License Plate: LW04FCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V11.80

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (1)

System	Status/DTC
Engine	0



DTC (0)

Technician Notes

2017283390

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

