



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260909095533
Test Time: 2026-09-09 09:55:33
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P507151225

Odometer Reading: 164838km
License Plate: HFG367L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (1)

System	Status/DTC
Engine	0



DTC (0)

Technician Notes

2017296263

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.