

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/CX-3/--

VIN: JM6DK2W7AM1500594

Odometer Reading: 123176

License Plate: JV16TZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V9.31

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned (10)

System	Status/DTC
PCM(Powertrain control module)	 0
TCM(Transmission control module)	 0
ABS(Anti-lock brake system)	 0
RCM(Restraint control module)	 0
IC(Instrument cluster)	 0
EPB(Electric parking brake)	 1
EPS(Electronic-controlled power steering)	 0
BCMM(Body control module)	  0
ESU(Electric supply unit)	 0
SSU(Start stop unit)	 0

DTC (1)

EPB(Electric parking brake) (1 DTC)

DTC	Description	Status
C1020:68-8B	Brake System Fill Not Complete	CMDTCs

Technician Notes

2017298562

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.