



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260916110535
Test Time: 2026-09-16 11:05:35
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--
VIN: KMFZBX7BLGU284159

Odometer Reading: 113124
License Plate: MY68SYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (1)

System	Status/DTC
ENG (Engine)	0



DTC (0)

Technician Notes

2017299377

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

