



Shop Name: --

Tel: --

Email: --

Address: --

Report ID: MAXIA20260915131308

Test Time: 2026-09-15 13:13:08

Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-100 Truck(HR)/--
VIN: KMFZBX7BLPU019090

Odometer Reading: 200316
License Plate: LB31BCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (1)

System	Status/DTC
ENG (Engine)	0



DTC (0)

Technician Notes

2017299105

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

