

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Elantra(MD)/--
VIN: KMHDH41CLDU893896

Odometer Reading: 139674
License Plate: JD29CMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
ENG (Engine)	 2
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 2
CLU (Cluster Module)	 0
A/C (Air Conditioner)	 1
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
BCM (Body Control)	 0
SJB (Smart Junction Block)	 2

DTC (9)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0335	Crankshaft position (CKP) sensor 'A' circuit	Active
P0504	Brake switch A/B Correlation	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History

B1346:00	Driver airbag (DAB) resistance too high (1st Stage)	History
----------	---	---------

A/C (Air Conditioner) (1 DTC)

DTC	Description	Status
B1685	Engine speed fault - CAN Signal	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C2412	Motor circuit open or short	History

SJB (Smart Junction Block) (2 DTCs)

DTC	Description	Status
B2519	Left rear turn signal lamp circuit open	History
B2521	Right rear turn signal lamp circuit open	History

Technician Notes
2017298906

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.