



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231212110702
Test Time: 2023-12-12 11:07:02
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)/--
VIN: KNAB2512LNT873577

Odometer Reading: 103767km
License Plate: KLT367MP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.40

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(11)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
i-TPMS (I-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
RVM (Rear View Monitor)	  0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2016198642

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.