

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Picanto/Morning (JA)/--  
VIN: KNAB3512LPT995373

Odometer Reading: 140415KM  
License Plate: KW76MFGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V14.10

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 11 )

| System                                                 | Status/DTC                                                                                                                                                                  |
|--------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ENG (Engine)                                           |  0                                                                                       |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) |  0                                                                                       |
| AB (Airbag)                                            |  1                                                                                       |
| CLU (Cluster Module)                                   |  0                                                                                      |
| I-TPMS (I-Tire Pressure Monitoring System)             |  0                                                                                     |
| A/C (Air Conditioner)                                  |  0                                                                                     |
| BCM (Body Control)                                     |  0                                                                                     |
| IMMO (Immobilizer)                                     |  0                                                                                     |
| CODE (Transmitter Code Saving)                         |  0                                                                                     |
| EPS (Motor Driven Power Steering)                      |  0                                                                                     |
| RVM (Rear View Monitor)                                |   0 |

## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

| DTC      | Description         | Status  |
|----------|---------------------|---------|
| B1102:00 | Battery voltage low | History |

## Technician Notes

2017297515

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.