



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20241111111346

Test Time: 2024-11-11 11:13:46

Technician: Andrick

# ChangAn VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/ChangAn/Chana/--

VIN: LSCAB13RXKG805521

Odometer Reading: 80155km

License Plate: JW70FMGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information


Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V12.50

Repair Order Number: --

## System Scanned( 1 )

System	Status/DTC
ECM (Engine system)-M788 (EA12) - UAES	 0

## DTC ( 0 )

## Technician Notes

2016606537

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

