



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20251030092034
Test Time: 2025-10-30 09:20:34
Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851CLGM468407
Odometer Reading: 119931
License Plate: DNS372L

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.90
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 2
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (3)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

Technician Notes

2017057124



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.