

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851CMFM140549

Odometer Reading: 133418
License Plate: DL43KXGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 3
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SJB (Smart Junction Block)	 2

DTC (6)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History
B2505:00	Passenger airbag (PAB) On/Off warning lamp failure	History

SJB (Smart Junction Block) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

B2519:00	Right cornering lamp circuit short to ground	History
B2521:00	Right rear turn signal lamp circuit open	History

Technician Notes
2017295873

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.