

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--
VIN: MALAF51CLLM095617

Odometer Reading: 316660KM
License Plate: JL97JSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 3
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (3)

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B1328:00	Driver front impact sensor (FIS) defect	History

Technician Notes

2017297476

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.