



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260911130235
Test Time: 2026-09-11 13:02:35
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Almera/--
VIN: MDHBBAN17Z0737389

Odometer Reading: 199104km
License Plate: KV33WJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine	 0
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 1
BCM	 1
IPDM E/R	 0

DTC (2)

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1606	Electric power steering (EPS) motor	Past

BCM (1 DTC)

DTC	Description	Status
B2190	Nissan anti-theft system (NATS) antenna AMP	Past

Technician Notes

2017297765

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

