

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Nissan Magnite/--
VIN: MDHFBADD0Z0020650

Odometer Reading: 30668
License Plate: KYZ442NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 1
Air bag	 0
Electric Power Steering (EPS)/DAST 3	 3
BCM	 7
HVAC	 1
Multi AV	 1
Hands-free module	 0
GWD 2	 0

DTC (13)

ABS (1 DTC)

DTC	Description	Status
C1073:1C	Vacuum sensor circuit 4.DEF	Past

Electric Power Steering (EPS)/DAST 3 (3 DTCs)

DTC	Description	Status
C1601:16	Battery voltage 1.DEF	Past
C161A:82	Vehicle speed multiplexed information 1.DEF	Past
C161B:86	Information multiplex vehicle speed invalid 1.DEF	Past

BCM (7 DTCs)

DTC	Description	Status
B1520:14	Starter relay C0.0	Past

B1563:01	Brake pedal contact circuit 1.DEF	Past
C1A60:7B	Under inflated ---	Crnt
C1A73:7A	Wheel 2 flat ---	Past
C1A74:7A	Wheel 3 flat ---	Crnt
C1A75:7A	Wheel 4 flat ---	Past
B120F:16	Voltage control 1.DEF	Past

HVAC (1 DTC)

DTC	Description	Status
B24C6:14	Blower motor control circuit CO.0	Past

Multi AV (1 DTC)

DTC	Description	Status
B1351:4B	ECU 1.DEF	Past

Technician Notes
2017296576

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.