



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260910094426
Test Time: 2026-09-10 09:44:26
Technician: Andrick

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP300 Navara/--
VIN: MNTCB2D23Z0001049

Odometer Reading: 255705km
License Plate: HV73CTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 0
Air bag	 0
Meter/M&A	 0
BCM	 0
HVAC	 0
IPDM E/R	 0
EMCM	 0
Headlamp levelizer	  0

DTC (0)

Technician Notes
2017296822

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.