

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/SONET(QY)/--

VIN: MZBFC814LMN083421

Odometer Reading: 63196km

License Plate: KB76WRGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V13.40

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(14)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	0
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
A/C (Air Conditioner)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
AVN (Audio Video Navigation)	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
ICU (Integrated Central Control Unit)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
RVM (Rear View Monitor)	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0

DTC (0)

Technician Notes

2016219218

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.