

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Juke(2WD)--
VIN: SJNFAAF15Z7196108

Odometer Reading: 139231km
License Plate: FK52HCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned (11)

System	Status/DTC
Engine	1
ABS	1
Air bag	1
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	1
BCM	1
HVAC	0
Multi AV	3
IPDM E/R	0
Multi-function display	0
AVM	1



DTC (9)

Engine (1 DTC)

DTC	Description	Status
P1550	Bat current sensor	1 time

ABS (1 DTC)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage (Low)	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1601	Battery VOLT	Past

BCM (1 DTC)

DTC	Description	Status
B2562	Low voltage	Past

Multi AV (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
U1263	USB overcurrent	Past
U12B0	Supply voltage below 9V	Past

AVM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes
2017296500

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.