

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/16 - Jetta 2011 >/--
VIN: WVVZZZ16ZJM013012

Odometer Reading: 206283
License Plate: HJ22FTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
01 - Engine Control Module 1	 2
03 - Brakes 1	 1
08 - Air conditioning	 0
09 - Electronic central electric	 3
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 0
42 - Driver's door electronics	 1
44 - Power steering	 0
52 - Passenger's door electronics	 1
5F - Information electronics 1	 0
61 - Battery Regulation	 1

DTC (9)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P007000	Ambient Air Temperature Sensor Circuit	Passive/Sporadic
P042000	Catalyst System Efficiency Below Threshold Bank 1 No Sub Type Information	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
01826:000	Steering angle sensor, voltage supply terminal 30	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
01500:010	Right fog light bulb - Open circuit/short circuit to B+	Active/static
01598:011	Drive battery voltage - Open circuit	Passive/Sporadic
02746:010	Right daytime running lamp bulb - Open circuit/short circuit to B+	Active/static

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B11F029	Driver side window regulator button Range/performance	Passive/Sporadic

52 - Passenger's door electronics (1 DTC)

DTC	Description	Status
B11FD01	Turn signal in exterior rear-view mirror Electrical error	Active/static

61 - Battery Regulation (1 DTC)

DTC	Description	Status
01598:003	Drive battery voltage - mechanical malfunction	Passive/Sporadic

Technician Notes

2017299013

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.