

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: WVVZZZ60ZBT057528

Odometer Reading: 261893
License Plate: BN02SSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	 3
02 - Transmission electronics	 0
03 - Brakes 1	 0
09 - Electronic central electric	 0
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 0
44 - Power steering	 0
56 - Radio	 0

DTC (3)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
17834:000	Evaporativ Emiss.System Purge Control Valve Circ. Open	Active/static
16686:000	Cyl.2 Misfire Detected	Passive/Sporadic
16684:000	Random/Multiple Cylinder Misfire Detected	Active/static

Technician Notes

2017297406

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.