



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/09/2026		M57 Pretoria Road - 1619
Inspection Date	16/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	JTF418MP
Model	FIGO 1.5 TREND 5-DR [2018-2021]	Register Number	
VIN	MAJGXXMTKGJG47191	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2026
Color	GOLDEN	Power / Displacement	
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	110,448 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:

2017299368

DATE

16/09/2026

Damage

Repair Way

Center Console / Cubbyhole + Lid Damaged	Repair
Seat Front Left Damaged	Repair
Seat Front Right Torn / Cut	Repair
Sun Visor Left Damaged	Replace
Sun Visor Right Damaged	Repair
Hood Lining Damaged	Repair
Gear Lever Dust Boot Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Windscreen Chipped	Repair
Service light on	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.9	3.2	-	
Rear	1.4	1.4	-	
Emergency / Parking	1	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Apollo	Alnac	V	3718	3 mm
Front Right	175/65R14	82T	Sumitomo	Htr t5	V	0424	3 mm
Rear Left	175/65R14	82H	Apollo	Alnac	V	3218	2 mm
Rear Right	175/65R14	82H	Apollo	Alnac	V	3418	3 mm
Spare	175/65R14	82T	Apollo	Amazer	V	4920	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	U3003:16-08	BATTERY VOLTAGE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026

Vehicle		Car		2017 Ford EcoSport 1.6T	
Model		EcoSport		1.6T	
Registration		11-11		11-11	
Test date		11-11		11-11	
Test time		11:41		11:41	
Test results		Pass		Pass	
Side slip test		Pass		Pass	
Shock absorber test		Pass		Pass	
Brake test		Pass		Pass	


Shock and brake report

Vehicle		Car		2017 Ford EcoSport 1.6T	
Model		EcoSport		1.6T	
Registration		11-11		11-11	
Test date		11-11		11-11	
Test time		11:41		11:41	
Test results		Pass		Pass	


Diagnostic report

Vehicle		Car		2017 Ford EcoSport 1.6T	
Model		EcoSport		1.6T	
Registration		11-11		11-11	
Test date		11-11		11-11	
Test time		11:41		11:41	
Test results		Pass		Pass	

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:

2017299368

DATE

16/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:

2017299368

DATE

16/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expenditure bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026



Oil cap and dipstick



Seat Front Left



Sun Visor Left



Sun Visor Right



Hood Lining



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026



Water level



Bonnet



Windscreen



Gear Lever Dust Boot



Center Console / Cubbyhole + Lid



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026



Door Rear Right



Sill Panel Right



Side Mirror Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191



CONDITION REPORT



Report No:
2017299368
DATE
16/09/2026



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGJG47191