



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	14/09/2026		M57 Pretoria Road - 1619
Inspection Date	14/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	HX11CJGP
Model	I20 1.2 MOTION 5-DR [2018-2021]	Register Number	
VIN	MALBM51BLKM539338	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/03/2027
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	149,107 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Damage Repair Way

Seat Front Left Dirty	Repair
Seat Rear Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Flaking	Repair
A • Pillar Left Paintwork • Flaking	Repair
A • Pillar Right Paintwork • Flaking	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Rear Fender Right / Inner Tray Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Paintwork • Flaking	Repair
Rear bumper Residual Traces of Repair	Repair
Sill Panel Right Residual Traces of Repair	Repair
Roof Residual Traces of Repair	Repair
Shock Absorber Rear Left Sweat	Replace
Rear Axle Welded	Replace
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.3	2.5	-	
Rear	1.6	1.6	-	
Emergency / Parking	1	0.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	88T	Firestone	Touring	V	2121	1 mm
Front Right	185/70R14	88T	Firestone	Touring	V	2121	1 mm
Rear Left	185/70R14	88T	Firestone	Touring	V	2121	1 mm
Rear Right	185/70R14	88T	Firestone	Touring	V	2121	3 mm
Spare	185/70R14	88T	Goodyear	Assurance	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338

**CONDITION REPORT**

Report No:
2017298571
DATE
14/09/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on body panels. Residual traces of poor repair on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:

Report No.
2017298571

DATE

14/09/2026

[illegible]

Shock and brake report

AUTEL No fault •
 12/1/2004 12:00
 12/1/2004 12:00

HYUNDAI VEHICLE DIAGNOSTIC REPORT

Vehicle Information
 VIN: 5N1MA08D22A000000
 Year: 2004
 Make: HYUNDAI
 Model: ACCENT
 Engine: 1.8L I4
 Transmission: 5-Speed Manual

Engine Scanned (3)

Code	Description	Count
P0121	MAP Sensor Voltage	1
P0122	MAP Sensor Voltage	1
P0123	MAP Sensor Voltage	1

Transmission Scanned (0)

Code	Description	Count
------	-------------	-------

ABS Scanned (0)

Code	Description	Count
------	-------------	-------

Brake Scanned (0)

Code	Description	Count
------	-------------	-------

Engine (3)
 12/1/2004 12:00

Transmission (0)
 12/1/2004 12:00

ABS (0)
 12/1/2004 12:00

Brake (0)
 12/1/2004 12:00

Print **Exit** **Back** **Home**

Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT




Report No:

2017298571

DATE

14/09/2026



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:

2017298571

DATE

14/09/2026



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



REAR



Coolant reservoir

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Oil cap and dipstick



Bonnet



Seat Rear



A • Pillar Right



Sill Panel Right



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT




Report No:
2017298571
DATE
14/09/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Front Fender Right



Door Front Right



Side Mirror Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Rear Fender Right



Roof



Roof



Seat Front Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Front Bumper



Rear bumper



Rear bumper



Rear bumper



Rear Fender Right / Inner Tray



Rear Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Rear Fender Right / Inner Tray



Rear Fender Right / Inner Tray



Gearbox



Belly plates



Shock Absorber Rear Left



Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338



CONDITION REPORT



Report No:
2017298571
DATE
14/09/2026



Rear Axle



Rear Fender Right / Inner Tray



Sill Panel Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51BLKM539338