



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 18/08/2025        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 18/08/2025        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |            |
|-----------------|-------------------|-------------------------|------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC        |
| Manufacturer    | RENAULT           | Registration Number     | NO REG     |
| Model           | KWID              | Register Number         |            |
| VIN             | MEEBBA00900622184 | Date Of First Licensing |            |
| Engine Number   |                   | Last COR                |            |
| Doors           | 5                 | License Expiry Date     |            |
| Color           | WHITE             | Power / Displacement    |            |
| Year Model      |                   | Paint Finish            | C - COMMON |
| Km Reading      | 35,406 KM         | Fuel                    | PETROL     |
| Cab / Body Type | HATCHBACK         | Transmission            | AUTOMATIC  |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: MEEBBA00900622184



CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025

|  | Damage                                       | Repair Way |
|-----------------------------------------------------------------------------------|----------------------------------------------|------------|
|                                                                                   | Engine Oil Leak                              | Repair     |
|                                                                                   | Battery clamps Defective                     | Repair     |
|                                                                                   | Front Fender Right Residual Traces of Repair | Repair     |
|                                                                                   | Main Beam Left Residual Traces of Repair     | Repair     |
|                                                                                   | Main Beam Right Residual Traces of Repair    | Repair     |
|                                                                                   | Radiator Cradle Residual Traces of Repair    | Repair     |
|                                                                                   | Warning lights illuminated                   | Repair     |
|                                                                                   | Exhaust leak                                 | Repair     |
|                                                                                   |                                              |            |

Brakes  
Brake Test Results

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s²] |
|---------------------|--------------------|--------------------|------------------|---------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                     |
| Front               | 1.6                | 1.7                | -                |                     |
| Rear                | 0.7                | 0.7                | -                |                     |
| Emergency / Parking | 0.8                | 0.8                | -                |                     |

Tyres and Rims  
Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model  | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|--------|-------|-----------------|------------------|
| Front Left  | 155/80R13 | 79T              | Ceat        | Milaze | V     | 3918            | 3 mm             |
| Front Right | 155/80R13 | 79T              | Ceat        | Milaze | V     | 3918            | 3 mm             |
| Rear Left   | 155/80R13 | 79T              | Ceat        | Milaze | V     | 3918            | 6 mm             |
| Rear Right  | 155/80R13 | 79T              | Ceat        | Milaze | V     | 3918            | 6 mm             |
| Spare       | 155/80R13 | 79T              | Roadking    | Argos  | V     | 0000            | 5 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System    | Code      | Description                                            | Status |
|----|-----------|-----------|--------------------------------------------------------|--------|
| 1  | INJECTION | DTC019517 | ENGINE OIL TEMPERATURE SENSOR BATTERY VOLTAGE TOO HIGH |        |

### Inspection Conditions

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on some body panels.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: MEEBBA00900622184




## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025




Shock and brake



Diagnostic test



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184



## CONDITION REPORT




Report No:  
2016983034  
DATE  
18/08/2025




90 DEGREE REAR



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184



## CONDITION REPORT




Report No:  
2016983034  
DATE  
18/08/2025



Sparewheel



No license disc



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025



Rear end



Exhaust damage



Oil cap



Dipstick



Coolant reservoir



Warning lights illuminated

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025



Engine



Engine



Engine



Radiator Cradle



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025



Radiator Cradle



Main Beam Left



Main Beam Left



Main Beam Left



Main Beam Right



Main Beam Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184



## CONDITION REPORT



Report No:  
2016983034  
DATE  
18/08/2025



Main Beam Right



Front Fender Right



Battery clamps

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MEEBBA00900622184