



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	04/09/2026		M57 Pretoria Road - 1619
Inspection Date	04/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	OPEL	Registration Number	BW07BDZN
Model	CORSA 1.2 EDITION 5-DR [2021-2022]	Register Number	
VIN	VXKUPHMGBN4233398	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2026
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	47,786 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXKUPHMGBN4233398



CONDITION REPORT




Report No:

2017294338

DATE

04/09/2026



Damage

Repair Way

Indicator Light Front Left Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Side Mirror Left Damaged	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Damaged	Repair
Windscreen Chipped	Repair
Spare Tyre Damaged	Repair
Belly plates Damaged	Repair
Triangle Damaged	Replace
Warning lights illuminated on dashboard	Repair
Bonnet release handle damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.02	3.07	-	
Rear	2.36	2.51	-	
Emergency / Parking	1.44	1.47	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Velocity	Rota-R	V	1624	1 mm
Front Right	185/65 R15	88H	Velocity	Rota-R	V	1624	2 mm
Rear Left	185/65 R15	88H	Continental	Eco contact	V	1422	2 mm
Rear Right	185/65 R15	88H	Goodyear	Efficient	V	0722	2 mm
Spare	185/65 R15	88H	Continental	ContiEco	V	1422	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BUILT-IN SYSTEMS INTERFACE(BSI)--BSI2010_EV	U1F3B:87	NO COMMUNICATION WITH MULTI-FUNCTION CONTROL UNIT OR THE WARNING LAMP FO SEATBELT NOT FASTENED	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine bay dirty.

Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels.

Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026

VEHICLE INFORMATION			
Make/Model	Car	Owner	Owner's Name
Year	2017	Make/Model	2017
Engine	2000 cc	Engine	2000 cc
Transmission	Manual	Transmission	Manual
Color	White	Color	White
VEHICLE CONDITION		VEHICLE CONDITION	
Exterior	Good	Interior	Good
Engine	Good	Transmission	Good
Brake	Good	Steering	Good
Shock Absorber	Good	Wheels/Tyres	Good
Light	Good	Bodywork	Good
Sound	Good	Overall	Good
TEST RESULTS		TEST RESULTS	
Brake	Pass	Shock Absorber	Pass
Light	Pass	Sound	Pass
Engine	Pass	Transmission	Pass
Steering	Pass	Wheels/Tyres	Pass
Bodywork	Pass	Overall	Pass

Brake and shock absorber report

VEHICLE DIAGNOSTIC REPORT	
Make/Model	Car
Year	2017
Engine	2000 cc
Transmission	Manual
Color	White
VEHICLE CONDITION	
Exterior	Good
Interior	Good
Engine	Good
Transmission	Good
Brake	Good
Shock Absorber	Good
Light	Good
Sound	Good
Steering	Good
Wheels/Tyres	Good
Bodywork	Good
Overall	Good

Diagnostic report page 1

VEHICLE DIAGNOSTIC REPORT	
Make/Model	Car
Year	2017
Engine	2000 cc
Transmission	Manual
Color	White
VEHICLE CONDITION	
Exterior	Good
Interior	Good
Engine	Good
Transmission	Good
Brake	Good
Shock Absorber	Good
Light	Good
Sound	Good
Steering	Good
Wheels/Tyres	Good
Bodywork	Good
Overall	Good

Diagnostic report page 2

VEHICLE DIAGNOSTIC REPORT	
Make/Model	Car
Year	2017
Engine	2000 cc
Transmission	Manual
Color	White
VEHICLE CONDITION	
Exterior	Good
Interior	Good
Engine	Good
Transmission	Good
Brake	Good
Shock Absorber	Good
Light	Good
Sound	Good
Steering	Good
Wheels/Tyres	Good
Bodywork	Good
Overall	Good

Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMG8N4233398




CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



Oil cap and dipstick



Bonnet release handle



Seat Front Right



Windscreen



Side Mirror Left



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



Rear Fender Left



Seat Front Left



Rear bumper



Rear bumper



Triangle



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT




Report No:
2017294338
DATE
04/09/2026



Front Fender Right



Side Mirror Right



Rear Fender Right



Rear Fender Right



Sill Panel Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



Front Bumper



Front Bumper



Grill



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398



CONDITION REPORT



Report No:
2017294338
DATE
04/09/2026



Belly plates



Belly plates



Belly plates



Belly plates



Belly plates



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VXXUPHMGBN4233398