



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	13/12/2024		M57 Pretoria Road - 1619
Inspection Date	13/12/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	BMW	Registration Number	JS09VKGP
Model	320I STEPTRONIC [2015-2019]	Register Number	
VIN	WBA8A16070NT98238	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/09/2024
Color	BLUE	Power / Displacement	
Year Model	2016	Paint Finish	TWO COAT UNI
Km Reading	304,623 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Hooter Defective	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Fog Light Front Left Missing	Replace
Fog Light Front Right Missing	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Door Panel Front Right Defective	Repair
Door Handle Front Left Defective	Repair
Door Handle Front Right Defective	Repair
Door Handle Rear Right Defective	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16070NT98238

1 / 22



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

Damage	Repair Way
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Defective	Repair
A • Pillar Left Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Paintwork • Scratched	Repair
Windscreen Damaged	Replace
Brake disc 2. Axle left Broken	Replace
Brake disc 2. Axle right Defective	Replace
Speed Sensor Damaged	Replace
Stabilizer Mounting Front Left Damaged	Replace
Rear Axle Defective	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Rear Left Defective	Replace
Tyre Rear Right Damaged	Replace
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Chassis Dented	Repair
Sub Frame Dented	Repair
Engine to silencer pipe Defective	Repair
Belly plates Damaged	Replace
Fuel Lines Defective	Repair
Radiator Cradle Damaged	Repair
Jack Missing	Replace
Triangle Damaged	Replace
Front right shock absorber weak	Replace
Undercarriage	Engine splash plate missing.
Brakes	Front left brake piping bracket loose.
Undercarriage	Front left Headlight leveling sensor missing.
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Signs of impact damage to front of vehicle.
Interior	Vehicle interior dirty and some panels scratched
Body and Exterior	Front emblem missing.
Warning light illuminated on dashboard	Repair
Axle and suspension	Front and rear suspension noisy
Tyres and rims	Spare wheel missing.
Tyres and rims	Front and rear tyre sizes different.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	3.53	3.46	-	
Rear	2.53	2.51	-	
Emergency / Parking	1.86	2.19	-	

Tyres and Rims

Tyre Specification & Measurement

VIN: WBA8A16070NT98238

2 / 22

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/35Z R19	93Y	Pirelli	Pzero	V	0721	0 mm
Front Right	255/40Z R18	99Y	Nexen	Nfera	V	3222	2 mm
Rear Left	255/40Z R19	96Y	Pirelli	Pzero	V	1516	0 mm
Rear Right	245/45 R19	98Y	Goodyear	Excellence	V	1919	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DME(ENGINE-DIGITAL MOTOR ELECTRONICS)	CD8F01	LIN, MESSAGE; INTELLIGENT BATTERY SENSOR(IFS): MISSING	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za




CONDITION REPORT

Report No: 2016660635


DATE
13/12/2024




Brake and shock absorber repor




Shock absorber readings




Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3



Diagnostic report page 4

N: WBA8A16070NT98238
3 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238
4 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Diagnostic report page 5



Diagnostic report page 6

Code	Description	Status
803286	Ultrasonic sensors rear centre left, signal line: line fault	Intermittent
804811	Undervoltage	Intermittent
894887	Overvoltage protection, light active	Intermittent
E50468	REM body CAN2: communication fault	Intermittent
DMA (Integrated Automatic Heating And A/C System) (2 DTCs)		
DTC	Description	Status
801180	Stratification control: Short circuit U B+ or interruption	Intermittent
801200	Undervoltage detected	Intermittent

Technician Notes
JIM FRANCOIS

Customer name:
Technician:
Date:

Print Please Wait 5 Copy of file records for your records.

Diagnostic report page 7



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

VIN: WBA8A10070NT98238
5 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238

6 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA8A16070NT98238



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



90 DEGREE LEFT




LF TYRE TREAD

VIN: WBABA16070NT98238
8 / 22



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238
9 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear Chassis



Front left brake piping bracket



Oil cap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238

11 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Spare wheel Accessories



Water level



Oil level



Center Console / Cubbyhole + Lid



Hood Lining



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

W/BAB/10070NT98238
12 / 22



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238
13 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Side Mirror Right



Door Handle Front Right



Door Handle Front Left



Door Panel Front Right



Door Handle Rear Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: WBA8A1G0701680625
Report No: 201680625

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Rear Fender Right



Door Rear Right



Door Front Right



Side Mirror Right



Front Fender Right



Fog Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238

16 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Headlight Left



Headlight Right



Fog Light Front Right



Front Bumper

VIN: WBA8A16070NT98238

17 / 22



Front Bumper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238
18 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Front Fender Left



Windscreen Wiper



Windscreen



Windscreen



A • Pillar Left



Side Mirror Left

VIN: WBA6A16070NT98238

19 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

VIN: WBA8A16070NT98238
20 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: WBA8A1G0701680635

21 / 22

DATE

13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Tail Light Left



Seat Front Left

VIN: W...16070NT98238
22 / 22



Triangle



Bolt(s) / Nut(s) Front Wheel Right



Rim Front Right



Front Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Hooter



Rocker Panel Right



Brake disc 2. Axle right



Bolt(s) / Nut(s) Rear Wheel Right



Rim Rear Right



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635


DATE
13/12/2024



Tyre Rear Left




Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Left



Brake disc 2. Axle left



Rear Fender Left / Inner Tray



Rocker Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Tyre Front Left



Engine Wiring



Front Fender Left / Inner Tray



Tyre Front Left



Speed Sensor



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024



Control Arm Bush(es) Front Axle Right



Stabilizer Mounting Front Left



Engine



Sub Frame



Engine Wiring



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635


DATE
13/12/2024



Tyre Rear Left



Rear Axle



Belly plates



Fuel Lines



Belly plates



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635


DATE
13/12/2024



Chassis



Engine to silencer pipe



Radiator Cradle



Bonnet slam plate (Shock tower/ Inner tray)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016660635

DATE
13/12/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za